

Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com



FLAMMABILITY TEST REPORT

Company Name & Address: BUTE FABRICS LTD

4 BARONE ROAD ROTHESAY ISLE OF BUTE PA20 ODP

Contact Name: SUZANNE MC GROARTY

Sample Details

Order No.: 3268

Description: Woven Upholstery

Ref. / Style No.: CF 840
Colour: Black / White
Quality: Lewis

Supplier: Bute
Batch No.: Not stated
End Use: Upholstery

Quoted Fibre Composition: 100% Pure New Wool

Retailer Not stated

Sample Description: Grey and white coloured woven fabric

| Test Method | Pre Treatment | Requirement | Result |
|---|---------------|--|-------------|
| BS 5852:2006 Clause 11 (upholstery composite) Ignition source 5 | None | As BS 5852:2006 Clause 11 (upholstery composite) Ignition source 5 | NI/5 (PASS) |

Note: The customer requested that RX36110 foam with an approximate density of 35 kg/m³ be used as the filling material

STEVEN OWEN ANDREW HALLETT CAROLE SPOWART GR
(Technical & Operational (Flammability Team Leader) (Flammability (Flammability)

Administrator)

GREGORY JAMES (Flammability Technician)

Report No.: LEI19110877A Page 1 of 2

Excellence Manager)











Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com



FLAMMABILITY TEST REPORT

Test Specification

Test Method: BS 5852:2006 Clause 11 (upholstery composite) Ignition source 5

Foam specification

Supplier / Grade: Carpenter / RX36110 (As requested by the customer)
Size: 450 x 450 x 75mm (back) & 450 x 300 x 75mm (seat)

Density / Hardness: 34-36kg/m³ /105-115N

Conditioning

Prior to Testing: At least 72 hours in ambient indoor conditions, then at least 24 hours in an atmosphere having a

temperature of 23 \pm 2°C and a relative humidity of 50 \pm 5%

At Time of Testing: Temperature of 10 °C to 30 °C and a relative humidity of 15 % to 80 %

Test Results

"The following test results relate only to the ignitability of the combination of upholstery composites (BS 5852: 2006, Clause 11) under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use":

| use"; | | | | | | | |
|--|---|----|---|----|--|--|--|
| Test number / position | 1 | 1 | 2 | 2 | | | |
| Criterion of Ignition | | | | | | | |
| Smouldering Criteria | | | | | | | |
| Externally detectable amounts of smoke, heat or glowing 60 minutes after crib ignition | No | | No | | | | |
| Escalating smouldering behaviour rendered the test unsafe to continue and required forcible extinction | No | | No | | | | |
| Smouldering essentially consumed the test specimen within the duration of the test / Smouldering reached the extremities of the test specimen (Other than the top of the vertical part of the test specimen) within the duration of the test | No | | No | | | | |
| Flaming Failure | | | | | | | |
| The test specimen continued to flame for more than 10 minutes after the ignition of the crib | No | | No | | | | |
| Escalating combustion behaviour rendered the test unsafe to continue and required forcible extinction | No | | No | | | | |
| Flaming essentially consumed the test specimen within the duration of the test | No | | No | | | | |
| Flaming reached the extremities of the test specimen (Other than the top of the vertical part of the test specimen) within the duration of the test | No | | No | | | | |
| Debris from the test specimen caused an isolated floor fire that continued to flame for more than 10 minutes after the ignition of the crib | No | | No | | | | |
| Final Examination | | | | | | | |
| Progressive smouldering was observed when the sample was dismantled | No | | No | | | | |
| Evidence of charring within the filling (other than discolouration) more than 100mm in any direction, apart from upwards, from the nearest part of the original position of the ignition source | No | | No | | | | |
| Time to extinction of flames after crib ignition | 3 Minutes 57 Seconds | | 4 Minutes 0 Seconds | | | | |
| Time to extinction of glowing after crib ignition | 5 Minutes 23 Seconds | | 5 Minutes 18 Seconds | | | | |
| Time to extinction of smoke after crib ignition | Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased | | Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased | | | | |
| Maximum extent of damage to back (mm) Length / Width | 400 | 84 | 400 | 85 | | | |
| Maximum extent of damage to base (mm) Length / Width | 65 | 90 | 65 | 92 | | | |
| Test Result | NI/5 (PASS) NI/5 (PASS) | | | | | | |
| Ignitability performance index: "Clause 11 - NI/5" | | | | | | | |

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI19110877A Page 2 of 2







